


## Tracking techniques with stretch

- Draw a rectangle 5000 x 3500 units
- Use the stretch command with tracking to create a rectangle of 3500 units width




Draw a rectangle 5000 x 3500 units



Start the stretch command (S) and select the right hand side of the rectangle as shown. Accept with enter and select a base point for the stretch.

Tracking point



Enter tracking by typing TK and pick any point on the left hand side of the rectangle as your tracking point. Then move the cursor to the right. You rae tracking from that point towards the right.



Type in the required value.